

TomTom ecoPLUS™ vehicle support matrix

Firmware version: 3.1.67

Date : 15/09/2012

This list shows all known vehicle models that have been equipped with TomTom ecoPLUS so far. Vehicle models not fully supported with the current firmware version are marked accordingly.

Brand	Model	Engine	Year	Comment
Alfa Romeo	Mito	1.3 Diesel	2011	
Audi	A3	1.6 Diesel	2010	
		1.9 Diesel	2007	
	A4	1.6 Gasoline	2001	
		2.0 Gasoline	2005	
		2.0 Diesel	2010 2011	
	A5	2.7 Gasoline	2008	
	A6	2.0 Diesel	2007	
BMW	118d	2.0 Diesel	2005	
	318i	2.0 Gasoline	2011	
	320d	2.0 Diesel	2010	
			2011	
	330i	3.0 Gasoline	2003 2007	
	520d	2.0 Diesel	2010	
	528i	2.8 Gasoline	2002	
	550i	4.4 Gasoline	2010	not working
	630i	3.0 Gasoline	2007	
	635d	3.0 Diesel	2008	
Mini	1.6 Gasoline	2010		
Citroën	Berlingo	1.6 Diesel	2008	
			2009	
			2011	
			2012	
	C3	1.6 Diesel	2007	not working
	C5	1.6 Diesel	2011	
	Jumper	2.2 Diesel	2012	
		3.0 Diesel	2010	
Jumpy	1.6 Diesel	2007		
		2008		

① requires TomTom ecoPLUS firmware version 3.1.45 or newer. ② requires TomTom LINK firmware version 1.9015 or newer. ③ Mercedes COTEL interface needs to be enabled. ④ requires TomTom ecoPLUS firmware version 3.1.58 or newer ⑤ contact Technical Support Hotline

				2011			
				2012			
		1.9	Diesel	2008			
DAF	CF 75	9.2	Diesel	2008			
				2009			
				2010			
				2012			
	CF 85	12.9	Diesel	2011			
	LF 45/55	4.5	Diesel	2007			
				6.7	Diesel	2008	
						2009	
	XF 105	12.9	Diesel	2011			
				2006			
				2007			
				2008			
2009							
Fiat	Croma	1.9	Diesel	2009			
	Ducato	2.3	Diesel	2011			
				3.0	Diesel	2009	
						2010	
						2011	
	Punto	1.2	Diesel	2010			
	Qubo	1.2	Diesel	2010			
	Scudo	1.6	Diesel	2010			
				2.0	Diesel	2008	
						2009	
						2010	
	2011						
Ford	C-Max	1.6	Gasoline	2010			
		2.0	Diesel	2009			
	Explorer	4.0	Gasoline	2006			
	Fiesta	1.4	Diesel	2008			
		1.6	Diesel	2011			
	Figo	1.4	Gasoline	2011			
	Focus	1.3	Diesel	2009			
				1.6	Diesel	2006	
						2008	
						2009	
2010							

① requires TomTom ecoPLUS firmware version 3.1.45 or newer. ② requires TomTom LINK firmware version 1.9015 or newer. ③ Mercedes COTEL interface needs to be enabled. ④ requires TomTom ecoPLUS firmware version 3.1.58 or newer ⑤ contact Technical Support Hotline

		1.8	Diesel	2006	
	Galaxy	1.9	Diesel	2003	
	Ka	1.2	Gasoline	2010	
	Mondeo	2.0	Diesel	2010	
		2.2	Diesel	2009	
	S-Max	2.0	Diesel	2006	
	Transit	1.8	Diesel	2004	not OBD-2 compliant
				2005	not OBD-2 compliant
		2.0	Diesel	2001	not OBD-2 compliant
				2002	not OBD-2 compliant
				2005	not OBD-2 compliant
		2.2	Diesel	2007	
				2008	
				2009	
				2010	
				2012	
		2.3	Gasoline	2008	
		2.4	Diesel	2005	not OBD-2 compliant
				2006	not OBD-2 compliant
	2007				
	2008				
	2009				
	2010				
	Transit Connect	1.8	Diesel	2006	
				2007	
				2008	
				2009	
				2010	
	Transit Luton	2.4	Diesel	2008	
				2011	
Ginaf	X Series	12.9	Diesel	2008	
				2010	
				2012	
Honda	Civic	1.4	Gasoline	2008	
				2010	
Hyundai	ix55	3.0	Diesel	2009	
	Tuscon	2.0	Gasoline	2008	
Iveco	Daily	2.3	Diesel	2007	
				2009	
				2010	

① requires TomTom ecoPLUS firmware version 3.1.45 or newer. ② requires TomTom LINK firmware version 1.9015 or newer. ③ Mercedes COTEL interface needs to be enabled. ④ requires TomTom ecoPLUS firmware version 3.1.58 or newer ⑤ contact Technical Support Hotline

				2011			
		3.0	Diesel	2007			
				2009			
				2010			
				2011			
	Eurocargo	3.9	Diesel	2010			
		5.9	Diesel	2007			
	Stralis	7.8	Diesel	2010			
		10.3	Diesel	2007			
				2008			
				2009			
				2011			
			12.9	Diesel	2007		
				2008			
				2010			
				2011			
Kia	Ceed	1.6	Diesel	2010			
Landrover	Discovery	2.7	Diesel	2008			
Lexus	GS	3.5	Gasoline	2008			
LDV	Convoy	2.4	Diesel	2005	not OBD-2 compliant		
MAN	TGA	10.5	Diesel	2005	not working		
				2006	not working		
				2007	not working		
	TGL/TGM	4.6	Diesel	2008	②④		
				6.9	Diesel	2007	②④
						2008	②④
						2009	②④
						2010	②④
	TGX/TGS	10.5	Diesel	2007	②④		
				2008	②④		
				2009	②④		
				2010	②④		
				2011	②④		
12.4		Diesel	2008	②④			
			2010	②④			
				2011	②④		
Mazda	2	1.2	Gasoline	2010			
	6	2.0	Diesel	2006			
Mercedes	Actros	11.9	Diesel	2006	①③		
				2007	①③		
				2008	①③		

① requires TomTom ecoPLUS firmware version 3.1.45 or newer. ② requires TomTom LINK firmware version 1.9015 or newer. ③ Mercedes COTEL interface needs to be enabled. ④ requires TomTom ecoPLUS firmware version 3.1.58 or newer ⑤ contact Technical Support Hotline

	Atego	4.2	Diesel	2009	① ③	
				2010	① ③	
				2011	① ③	
				2005	not OBD-2 compliant	
				2006	not OBD-2 compliant	
				2007		
		2008				
		2009				
		2011				
		2012				
		4.8	Diesel	2008		
				2009		
	2010					
	2011					
	6.4			Diesel	2008	
					2009	
		2011				
	Axor	11.9	Diesel	2008	⑤	
				2009	⑤	
				2010	⑤	
				2011	⑤	
	C200	2.0	Gasoline	2004		
	Citaro	12.0	Diesel	2008	⑤	
				2009	⑤	
	Integro	12.0	Diesel	2009	⑤	
	Sprinter	2.1	Diesel	2006		
				2007		
				2008		
				2010	①	
		2011	①			
3.0		Diesel	2008			
			2009			
	2010					
Vito / Viano	2.1	Diesel	2004			
			2005			
			2006			
			2007			
			2008			
	2011	①				
3.0	Diesel	2011	①			
Mitsubishi	Fuso	3.0	Diesel	2007		

① requires TomTom ecoPLUS firmware version 3.1.45 or newer. ② requires TomTom LINK firmware version 1.9015 or newer. ③ Mercedes COTEL interface needs to be enabled. ④ requires TomTom ecoPLUS firmware version 3.1.58 or newer ⑤ contact Technical Support Hotline

				2011	
				2012	
		5.0	Diesel	2011	
				2012	
	L200	2.5	Diesel	2011	
Nissan	Cabstar	2.5	Diesel	2011	
		3.0	Diesel	2011	
	Maxima	3.5	Gasoline	2004	
	NV200	1.5	Diesel	2010	
				2011	
	Primastar	2.0	Diesel	2011	
Terrano	2.7	Diesel	2004		
Opel / Vauxhall	Astra	1.2	Diesel	2011	
		1.6	Gasoline	2010	④
		1.7	Diesel	2006	
				2007	
	2010				
	Combo	1.3	Diesel	2006	
				2007	
				2008	
				2009	
				2011	
				2012	
		1.7	Diesel	2005	
				2008	
	Corsa	1.2	Diesel	2008	
				2009	
				2011	
	Meriva	1.6	Diesel	2008	
	Movano	2.3	Diesel	2011	
		2.5	Diesel	2008	
	Vivaro	1.9	Diesel	2003	not working
				2004	not working
				2005	not working
				2006	not working
2.0		Diesel	2007		
			2008		
			2009		
	2.5	Diesel	2007		
Zafira	1.8	Gasoline	2001		

① requires TomTom ecoPLUS firmware version 3.1.45 or newer. ② requires TomTom LINK firmware version 1.9015 or newer. ③ Mercedes COTEL interface needs to be enabled. ④ requires TomTom ecoPLUS firmware version 3.1.58 or newer ⑤ contact Technical Support Hotline

Peugeot	107	1.0	Gasoline	2010	
				2011	
				2012	
	308	1.6	Diesel	2009	
				2011	not working
	407	1.6	Diesel	2010	not working
	5008	1.6	Diesel	2011	
				2.0	Diesel
	Bipper	1.4	Gasoline	2010	
	Boxer	2.2	Diesel	2010	
				3.0	Diesel
				2009	
	Expert	1.6	Diesel	2009	
				2010	
				2011	
				2012	
	2.0	Diesel	2010		
			2011		
Partner	1.6	Diesel	2009	⑤	
			1.9	Diesel	2002
Renault	Clio	1.2	Gasoline	2009	
				2010	
				2011	
		1.5	Diesel	2010	
				2011	
	Espace	unknown			not working
	Kangoo	1.5	Diesel	2005	
				2008	
				2009	
				2010	
				2011	
	Laguna	2.0	Diesel	2009	
	Magnum	12.8	Diesel	2006	①
				2007	①
				2008	①
				2009	①
				2010	①
2011				①	
Master	2.3	Diesel	2010		
			2011		
	2.5	Diesel	2008	⑤	
Megane	1.6	Gasoline	2001		

① requires TomTom ecoPLUS firmware version 3.1.45 or newer. ② requires TomTom LINK firmware version 1.9015 or newer. ③ Mercedes COTEL interface needs to be enabled. ④ requires TomTom ecoPLUS firmware version 3.1.58 or newer ⑤ contact Technical Support Hotline

	Midlum	2.0	Gasoline	2010			
		4.8	Diesel	2010	①		
				2011	①		
	Premium	10.8	Diesel	2008	①		
				2009	①		
				2006	①		
				2008	①		
	Traffic	1.9	Diesel	2009			
				2.0	Diesel	2008	
						2010	
						2011	
						2012	
	2.5	Diesel	2010	not working			
	Scania	G/R/P Series	8.9	Diesel	2005		
2006							
2007							
9.3			Diesel	2010			
11.7			Diesel	2005			
				2006			
				2007			
				2008			
				2009			
				2010			
12.7			Diesel	2011			
				2007			
				2008			
				2009			
				2010			
15.6			Diesel	2011			
				2012			
				2005			
	2006						
	2008						
	2009						
Seat	Ibiza	1.4	Gasoline	2004			
	Leon	2.0	Gasoline	2007			

① requires TomTom ecoPLUS firmware version 3.1.45 or newer. ② requires TomTom LINK firmware version 1.9015 or newer. ③ Mercedes COTEL interface needs to be enabled. ④ requires TomTom ecoPLUS firmware version 3.1.58 or newer ⑤ contact Technical Support Hotline

Skoda	Fabia	1.2	Diesel	2010	
				2011	
		1.4	Gasoline	2003	
		1.4	Diesel	2009	
	Octavia	2.0	Diesel	2009	not working
Subaru	Impreza	2.5	Gasoline	unknown	
		2.0	Gasoline	2006	
Temsa	Safari	12.9	Diesel	2010	
Toyota	Auris	1.4	Diesel	2009	
		2.0	Diesel	2008	
	Camry	2.5	Gasoline	2011	
	Hilux	2.5	Diesel	2009	
	Yaris	1.0	Gasoline	2003	not working
				2008	
	1.4	Diesel	2009		
Van Hool	T 917	12.9	Diesel	2011	
	TD 927	12.9	Diesel	2008	
				2009	
				2010	
				2011	
				2012	
VDL/Bova	Futura	9.2	Diesel	2011	
		12.6	Diesel	2004	
				2006	
	Magiq	12.6	Diesel	2005	
		12.9	Diesel	2007	
				2009	
				2010	
Synergy	12.9	Diesel	2009		
Volkswagen	Caddy	1.6	Diesel	2010	
				2011	
				2012	
		1.9	Diesel	2008	
				2009	
				2010	
				2011	
				2009	
		2.0	Diesel	2005	
	2006				
	2007				
				2009	
	Crafter	2.0	Diesel	2012	

① requires TomTom ecoPLUS firmware version 3.1.45 or newer. ② requires TomTom LINK firmware version 1.9015 or newer. ③ Mercedes COTEL interface needs to be enabled. ④ requires TomTom ecoPLUS firmware version 3.1.58 or newer ⑤ contact Technical Support Hotline

		2.5	Diesel	2007	
				2008	
				2009	
				2010	
				2011	
	Golf	1.6	Diesel	2009	
				2010	
		1.9	Diesel	2001	
				2007	
				2009	
		2.0	Gasoline	2010	
	Golf Plus	1.6	Diesel	2010	
	Jetta	2.0	Diesel	2011	
	Passat	1.4	Gasoline	2011	
		1.9	Diesel	2006	
		2.0	Diesel	2008	
	Polo	1.2	Diesel	2011	
				2012	
		1.6	Gasoline	2006	
		1.9	Diesel	2005	
	Touran	1.9	Diesel	2005	
		2.0	Diesel	2007	
	Transporter	1.9	Diesel	2009	
		2.0	Diesel	2010	
				2011	
		2.5	Diesel	2007	
				2008	
	Up	1.0	Gasoline	2012	
Volvo	C30	1.6	Diesel	2010	①
	FH / FM / FMX	12.8	Diesel	2007	① ②
				2008	① ②
				2009	① ②
				2010	① ②
				2011	① ②
	FL / FE	7.2	Diesel	2010	
	S40	1.8	Gasoline	2007	
	S60	2.4	Diesel	2008	
	S80	2.4	Diesel	2008	
		2.5	Diesel	2007	
	V50	1.6	Diesel	2007	
		2.0	Diesel	2006	

① requires TomTom ecoPLUS firmware version 3.1.45 or newer. ② requires TomTom LINK firmware version 1.9015 or newer. ③ Mercedes COTEL interface needs to be enabled. ④ requires TomTom ecoPLUS firmware version 3.1.58 or newer ⑤ contact Technical Support Hotline

	V60	2.0	Diesel	2011	
	V70	2.4	Diesel	2010	
	XC60	2.0	Diesel	2011	
		2.4	Diesel	2009	
				2010	
	XC70	2.4	Diesel		

① requires TomTom ecoPLUS firmware version 3.1.45 or newer. ② requires TomTom LINK firmware version 1.9015 or newer. ③ Mercedes COTEL interface needs to be enabled. ④ requires TomTom ecoPLUS firmware version 3.1.58 or newer ⑤ contact Technical Support Hotline